




REPAIR and OVERHAUL CAPABILITIES for CFM56-7B VBV SYSTEM



TAT: 15-20 days
Attractive Flat Rate or
Time & Material
available.
Repairs under FAA,
EASA certifications

P/N	DESIGNATION	ATA CHAPTER
340-402-602-0	VBV Actuator	75-32-14
340-402-603-0		
340-402-604-0		
340-402-653-0		
340-056-804-0	VBV Actuating Ring	72-23-16
340-074-402-0	VBV Doors	
340-074-505-0	VBV Hinges	
340-079-204-0	VBV Rod	
340-168-601-1	VBV Bellcranks	
340-168-701-0		
340-085-202-1		
340-085-302-0		
340-085-451-0	VBV Turn buckles	
340-085-401-0		
340-085-402-0		
340-168-301-0		
340-168-351-0		

For **more information**, please contact your **Sales Representative** at:
+33 (0)5 62 07 50 60