



CFM56 and CF 34 Lubrication System




Pressure switch



DMS Sensor



Lub Unit



Oil Tank



Chip Detector

... and many more

TAT : 15 – 20 days - Attractive Flat Rate or Time & Material available

Repairs under FAA, EASA, CAAC certifications

For more information, please contact your Sales Representative at:

+33 (0)5 62 07 50 60